


The two 20-pole connectors seen from the rear side (solderside).



* The function is established when the pin is connected to 0 Volt.

□ The function is established when the pin is connected to → Supply voltage.